

Umrechnungstabelle bar / psi
Conversion table bar / psi

| | 0 | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 |
|-----|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|
| bar | psi | psi | psi | psi | psi | psi | psi | psi | psi | psi |
| 0 | . | 14,5035 | 29,0070 | 43,5105 | 58,0140 | 72,5175 | 87,0210 | 101,5245 | 116,0280 | 130,5315 |
| 10 | 145,0350 | 159,5385 | 174,0420 | 188,5455 | 203,0490 | 217,5525 | 232,0560 | 246,5595 | 261,0630 | 275,5665 |
| 20 | 290,0700 | 304,5735 | 319,0770 | 333,5805 | 348,0840 | 362,5875 | 377,0910 | 391,5945 | 406,0980 | 420,6015 |
| 30 | 435,1050 | 449,6085 | 464,1120 | 478,6155 | 493,1190 | 507,6225 | 522,1260 | 536,6295 | 551,1330 | 565,6365 |
| 40 | 580,1400 | 594,6435 | 609,1470 | 623,6505 | 638,1540 | 652,6575 | 667,1610 | 681,6645 | 696,1680 | 710,6715 |
| 50 | 725,1750 | 739,6785 | 754,1820 | 768,6855 | 783,1890 | 797,6925 | 812,1960 | 826,6995 | 841,2030 | 855,7065 |
| 60 | 870,2100 | 884,7135 | 889,2170 | 913,7205 | 928,2240 | 942,7275 | 957,2310 | 971,7345 | 986,2380 | 1000,7415 |
| 70 | 1015,2450 | 1029,7485 | 1044,2520 | 1058,7555 | 1073,2590 | 1087,7625 | 1102,2660 | 1116,7695 | 1131,2730 | 1145,7765 |
| 80 | 1160,2800 | 1174,7835 | 1189,2870 | 1203,7905 | 1218,2940 | 1232,7975 | 1247,3010 | 1261,8045 | 1276,3080 | 1290,8115 |
| 90 | 1305,3150 | 1319,8185 | 1334,3220 | 1348,8255 | 1363,3290 | 1377,8325 | 1392,3360 | 1406,8395 | 1421,3430 | 1435,8465 |
| 100 | 1450,3500 | 1464,8535 | 1479,3570 | 1493,8605 | 1508,3640 | 1522,8675 | 1537,3710 | 1551,8745 | 1566,3780 | 1580,8815 |

psi = 0,0689 bar

Umrechnungstabelle psi / bar
Conversion table psi / bar

| | 0 | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 |
|-----|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|
| psi | bar | bar | bar | bar | bar | bar | bar | bar | bar | bar |
| 0 | . | 0,0689 | 0,1378 | 0,2067 | 0,2756 | 0,3445 | 0,4134 | 0,4823 | 0,5512 | 0,6201 |
| 10 | 0,6890 | 0,7579 | 0,8268 | 0,8957 | 0,9646 | 1,0335 | 1,1024 | 1,1713 | 1,2402 | 1,3091 |
| 20 | 1,3780 | 1,4469 | 1,5158 | 1,5847 | 1,6536 | 1,7225 | 1,7914 | 1,8603 | 1,9292 | 1,9981 |
| 30 | 2,0670 | 2,1359 | 2,2048 | 2,2737 | 2,3426 | 2,4115 | 2,4804 | 2,5493 | 2,6182 | 2,6871 |
| 40 | 2,7560 | 2,8249 | 2,8938 | 2,9627 | 3,0316 | 3,1005 | 3,1694 | 3,2383 | 3,3072 | 3,3761 |
| 50 | 3,4450 | 3,5139 | 3,5828 | 3,6517 | 3,7206 | 3,7895 | 3,8584 | 3,9273 | 3,9962 | 4,0651 |
| 60 | 4,1340 | 4,2029 | 4,2718 | 4,3407 | 4,4096 | 4,4785 | 4,5474 | 4,6163 | 4,6852 | 4,7541 |
| 70 | 4,8230 | 4,8919 | 4,9608 | 5,0297 | 5,0986 | 5,1675 | 5,2364 | 5,3053 | 5,3742 | 5,4431 |
| 80 | 5,5120 | 5,5809 | 5,6498 | 5,7187 | 5,7876 | 5,8565 | 5,9254 | 5,9943 | 6,0632 | 6,1321 |
| 90 | 6,2010 | 6,2699 | 6,3388 | 6,4077 | 6,4766 | 6,5455 | 6,6144 | 6,6833 | 6,7522 | 6,8211 |
| 100 | 6,8900 | 6,9589 | 7,0278 | 7,0967 | 7,1656 | 7,2345 | 7,3034 | 7,3723 | 7,4412 | 7,5101 |

bar = 14,5035 psi